



Computer System Architects
 950 N. University Avenue
 Provo, Utah 84604
 (801) 374-2300
 FAX: 374-2306

Transputer Education Kit User Guide Errata

15 Oct 1990

Please make the following corrections to the Transputer Education Kit User Guide:

Page 16


The program listed in section 2.5.3 is missing the first two lines. The following shows the proper placement of the first few lines of the listing:

```
pub _main
;
; Definitions.
```

Page 29

The following graphic in section 3.4.2 is in error. With one jumper installed, the user can select 20 Mbits/s for Link0 and 10 Mbits/s for Links 1,2 &3.

This is the corrected image:



Page 47

The schematic for the Eight Channel A to D Converter has an error that can destroy the chip. On the ADC 0808, VRef+ should come out on pin 12 and VRef- should come out on pin 16. The diagram on page 47 shows these two pin numbers reversed. Note also that Vcc for the ADC 0808 should be connected to pin 11 and Gnd to pin 13.

